

February 13, 2012



Re: House inspection at Old St. James Road, Rolla, MO

Dear

At your request, I inspected the above referenced house on February 10, 2012. Attached is a copy of the checklist utilized for the conduct of this inspection.

A summary of the results of the inspection is as follows:

- 1. The roof sewer vent boot is split and in need of repair.
- 2. The sliding screen door screen is torn.
- 3. The back deck is set on pads on top of the ground.
- 4. There is no deck stair handrail.
- 5. The steel brick lintels are rusted and are in need of painting.
- 6. The upstairs bedroom and dining room floors are unlevel due to uplift from the weight of the front exterior wall from the cantilevered floor joists, and the framing of the floor joists and the girders.
- 7. There is a chip in the fiberglass finish of one bathtub.
- 8. One toilet is loosely anchored to the floor.
- 9. The laundry tub is not anchored adequately and is loose.
- 10. There are stained drop ceiling tiles.

Example of our competitor's report

- 11. There is stained carpet.
- 12. The range top finish is damaged.
- 13. The dishwasher is not functional.

With the noted exceptions the house is well maintained, and is in general compliance with established building codes.

If you have any questions, please feel free to call me at

Sincerely,

Att.

	Address	Pou	JAV N. Nate	MES 2() Attend	2/10/12 ed (2) N	ROOF 1
LIMITATIONS	ROOF AS SEEN FROM:	STY		GENERA	L	SECTION
DOTYPICAL DE RESTRICTED No Access Too Steep Show and Ice Moisture or Fungus Hazardous	☐ Ground IN Eaves ☐ Walked ☐ Binoculars ☐ None (Not Seen)	\$####################################		System Inspected Estimated Age Number of Layers Estimated Remaining Life Prior Leaks (Cured) Active Leaks Flashing Leaks Amateur Workmanship Subjective Rating System Inspected Y N N N N N N N N N N N N N N N N N N		
ROOF	ING MATERIALS			OBSERVATION	IS	
IVASPHALT □ BUILT-UP □ Felt Matric Shingles □ 3 or 4 Ply with Gravel IVE Fiberglass Matrix Shingles □ 3 or 4 Ply Smooth □ Roll Roofing □ Other □ WOODEN □ METAL □ Shingles □ Flat Seam □ Shakes □ Standing Seam □ SLATE OR TILE □ Corrugated Tin □ Vermont or Buckingham □ Copper □ Bangor □ Aluminum □ Clay Tile □ SINGLE MEMBRANE □ Cement Tile □ Asbestos Cement Shingles			Sound		Broken king	
FLASHING AN	ND JOINT MATERIAL		C	BSERVATIONS		
☐ Galvanized Iron or Tin ☐ Tar ☐ Aluminum ☐ Neoprene (Rubber) ☐ Copper ☐ Roofing Material ☐ Lead ☐ None			D Sound D Split of Separated T 2 D Typical □ Tar on Flashing □ Exposed or Lifted Nails □ Leaking at Valley □ Rusted □ Leaking at Dormer □ Flashing Omitted		y ner	
<u>GUTTERS AN</u>	ID DOWNSPOUTS		Ç	BSERVATIONS	3	
GUTTER MATERIAL NONE ATTACHED Galvanized Iron or Tin Copper Vinyl or Plastic BUILT-IN SPLASHBOCKS DRAINTILE			☐ Rusted☐ Rotting	al Damage	☐ Sagging ☐ Debris ☐ Leaking ☐ Open Joints ☐ Rot/Damaged W	/ ood
VENTILATION		OBSERVATIONS				
Gable □ Roof Sofitt □ Window or Fan Bridge □ None □ Turbines □ Box Vents		☐ Physical Damage ☐ Condensation		nage		
MISCELLANEOUS SOFFITS AND FASCIAS GROUPE			<u>OBSERVATIONS</u>			
SOFFITS AND FASCIAS SKYLIGHTS Plastic Glass Operable		Sound Typical Leaking Narrow Fogged	g or No Overhang I Thermal Skyligh	☐ Leaking Skylight ☐ Cracked Glass ☐ Leaking at Other Roof Equipme		
Commente:						

LUMITATIONS		<u> </u>					SECTIO
<u>LIMITATIONS</u>						GENERAL	SPUTLEVEL
⅓ TYPICAL	☐ Topography/Si		em Inspected		N	Style	STORY WIBSMT
RESTRICTED	☐ Attached or less Clues		s/Tell tales	Y	$\stackrel{\circ}{\mathbb{O}}$	Walls Plumb	D N
☐ Vegetation	_ 3 ft. Clearand	e Alert	to Toxins	Υ	(A)	Amateur Work	manship Y
Vines	☐ Personal Prope		r Defects	Y		Subjective Rat	
Shrubbery		Site	_	\bigcirc	N	•	۱ ۱۱۱۰ ویوت
EXTER	OR SIDING MA	TERIALS				OBSERVAT	IONE
MASONRY		wood		MSound	-		
Ø Brick		ck Veneer		ØSound ØTypica			□Wicking
Stone	Ø Vinyl/Aluminum						☐ Too Low
□ Block	□ Stu	icco		□Buckli			☐ Cracked
☐ Adobe		ment Asbestos		☐ Paint I			Spalling
☐ FRAME				☐ Rot or ☐ Attach	Spiasn		Movement
☐ Hardboard				☐ Vines	1116111		☐ Mortar Damage ☐ Efflorescence
☐ Wood				Delam	inate		☐ Mildew
☐ Shingle				Loose			L Mildew
EXTERI	OR TRIM			<u> </u>		CEDVATIONS	
□Wood		∯Sound		_		SERVATIONS	
Vinyl and/or Alumi	num	Σ∳Typical			Attachment		☐ Too Low
ye any ana, or , aarrii	ium	Paint Fa	ilina		/ines		☐ Post or Column
		☐ Rot or S		□ L	.oose		☐ Flashing Omitted
PRIMAR	RY WINDOWS		Pidan	· · · · · · · · · · · · · · · · · · ·			
ØMATERIAL				۱		OBSERVATI	<u>ONS</u>
Wood	☐ Fix	kea Ilousie		Sound			ilazing Failing
☐ Aluminum		AZING		[⊅ Typica			elayed Maintenance
☐ Steel		ngle Glass		☐ Paint F	ailing		lusted
Plastic or Vinyl		sulated Glass		☐ Rot or ☐ Vines	Splash		hysical Damage
Clad		ple Glass		□ vines □ Too Lo		LACT-	unctional
Ø TYPE	DF sc	REENS		☐ Cracke			
12 Double Hung			N/P/A/D				
☐ Casement			V/P/A/D		ng Omitted n or Missing	_	
AS Sliding			V/P/A/D	Lost S	n or missing	3	
☐ Awning	,	•	41.7.40		Cui		
FYTER	OR DOORS						
Ø ENTRY	<u></u>	latal				OBSERVATION	<u>ONS</u>
Wood	<u>-</u>	letal		_ ⊈Sound			lisalignment
© Metal	Z TYI	iberglass		Ø Typica	J	□N	one or Damaged
A SLIDING		~⊑ ∕erhead		Paint F	Failing	1	Weatherstripping
□ Wood		remead nged		☐ Rot or	Splash	□o	pener Failure
Aluminum/Vinyl		olling		Delam			
☐ FRENCH/ATRIUM		ERATION		□ Flashir	ng Omitted		
☼ GARAGE DOORS		anual		☐ Lost Se	eai		
MATERIAL		itomatic		To Physic	ı al Damage		
□ Wood	,			4 Filysic		SLIDING	DOOR SCREEN
PORCH	ES AND DECKS		T			SERVATIONS	Depic SCREEK
☐ Wooden Porches		reened Porches	Ľ2kSound				
Masonry Stoops	DØ Pa	tio	Typical				☐ Flashing Omitted
🕅 Decks			☐ Paint Fai	lina	□ Mo	vement	□Settlement
			☐ Rot or S			st or Column	☐ or Rotation
STEPS /	AND RAILS					SERVATIONS	00 70p 0FBD
☐ Masonry Steps	□ Me	tal Rails	Д % Sound				
₩wood Steps	D Wα	od Rails	De Typical			achment	Settlement
•		yl Rails	☐ Paint Fail	lina	☐ Loc	· -	or Rotation
		•	☐Rot or Sp		☐ Rus		MONO Rails DECK
GARAC	SES AND CARP	ORTS	<u>'</u>			RVATIONS	STAIR MANDRAIL
☐ Detached	☐ Det		Ş ∂Sound			Firewall	
Attached		uildings	Z Typical		□ 140	ı ıı Cwall	☐ Not Inspected
FIRE ES			<u> </u>			CEDVATIONS	☐ None Present
□ None	/		□Sound			SERVATIONS	-
☐ Exterior			☐Typical		⊔ Atta	chment	☐ Rusted
_	/		,piou				☐ Physical Damage
Comments:	anla a	4	K 00	100 K	\ \	torlo	roport

3

LIMITATIONS			2=11==		SECT
TYPICAL RESTRICTED Access Too Small Too Low	Wet/Hazardous Ina Vermin or Insects Personal Possessio Lower Level Finished	Evidence of Prior Wa Dons/Debris Evidence of Wood Ea Evidence of Structura		ter ating Insects al Distress	2 6 2 2 2 2 2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4
FOUNDATION	1		OBSERVATIO	ONG	E (A) W F
☐ TYPE ☐ Crawlspace ☐ Basement ☐ Slab ☐ Combination ☐ Piers	MATERIAL Brick Block Brick and Block Stone Concrete Wood Terra Cotta	Sound Sound Sound Exterior Cracked Evidence of Settlement No Settlement Noted Unstable Soil Basement Wall Cracked Basement Wall Buckling		☐ Pier or Colu ☐ Underminin	ımn Damage ig ge or Drainage
STRUCTURE AND M	MATERIALS				
MASONRY Brick Block	STEEL Girders Columns Lintels	Sound Sterior Cracked Cracked		☐ Trades Dam ☐ Undersized ☐ Undersized ☐ Amateur Wo ☐ Cut or Unre ☐ Cut or Damage ☐ Rot Damage ☐ Delamination ☐ Fire Damage ☐ Rusted Colu ☐ Temporary S ☐ Poor Bearing ☐ Delamination ☐ Fire Damage ☐ Rusted Colu ☐ Temporary S ☐ Poor Bearing ☐ Condensation	or Sagging Girder or Sagging Joists orkmanship paired Element aged Trusses e Roof Substructure e Roof Sheeting g Sheet Undersized Framing e umns Supports g
		□ Basem	Damaged nent Windows	☐ Musty Odor☐ Dehumidifier	r
		☐ Crawl	en/Damaged/Inoperable Space Wet or Damp	☐ Mold or Mild	lew
INTERIOR DRAINAG □ Sump Pump □ Floor Drains □ Drain Tile ISO Vapor Barrier □ None		OBSERVATIONS Functional Floor Drain Blocked Damaged Sump Pump Inoperable Sump Pump Damaged or Improperly Instal Sump Dry Water on Top Vapor Barrier Install Proper Vapor Barrier		_	
EXTERIOR DRAINAG	<u>iE</u>			·	
⅓ SITE □ Level ℘ Sloping	IMPROVEMEN Swales Ditches Terraces Retaining Wa	☐ Negative Drainage Relief Dra ☐ Neutral Drainage		alls Lack Footing/ ins	
	☐ Drain Tile ☐ Window Well	s	☐ Freeze Thaw Damage ☐ Leaning/Over Turning R	etaining Wolle	
Comments		·	= = ==================================	craning walls	

Example of our competitor's report

<u> </u>			SECTIO
LIMITATIONS	<u>_</u>	GENERAL	
TYPICAL		System Inspected	Ø N
RESTRICTED		Water on	(A) N
☐ Crawlspace Inaccess	ible	Amateur Workmanship	Υ 🐧
Attic Inaccessible		Supply Private	Y 👧
House Unoccupied		Waste Private	P A T
1		Shut off location	DASTEMENT
		Estimated Age Water Hea Active Leaks	ter NIONRS
		Subjective Rating	
MAIN SUPPLY	/ LINE AND CULT OFF		EAM F
	LINE AND SHUT OFF	OBSERV	ATIONS
MATERIAL Copper	SHUT OFF VALVE	№ Sound	□ Drips or Leaks
□ Lead	☐ Crawispace Basement	Æ -Typical	No Vaive or Inaccessible
☐ Plastic	<u></u>	☐ Mechanical Damage	Ø Pressure Reducing Valve
□ Iron	□ Outside □ Meter	☐ Temporary Repairs	
		☐ Corrosion	
	ING LINE MATERIALS	OBSERV	ATIONS
SUPPLY PIPING	WASTE PIPING	D Sound	☐ Hanger Damage
Copper Galvanized	☐ Cast Iron	Ø Typical	☐ Improper Pitch
☐ Brass	☐ Galvanized	☐ Mechanical Damage	☐ Improper Traps
□ brass □ Lead	☐ Copper	☐ Temporary Repairs	☐ Lack of Vacuum Breakers
☐ Plastic	Plastic □ ABS	☐ Corrosion	☐ Sealed or Damaged Clean Outs
□ PVC	DA PVC	☐ Unsupported	☐ Unvented
□ CPVC	Lead	☐ Possible Asbestos	☐ Rain Leader into City Sewer
□ PB	☐ Clay	☐ Hot and Cold Too Close	☐ Wet Venting
□ PEX	☐ Other	☐ Runs off	☐ Sewer Ejector
☐ Other	☐ INSULATED OR	☐ Abandoned Piping☐ Failed Pressure Tank	☐ Fixture Below Outlet
	UNINSULATED	or Booster Pump	☐ Mixed Metal/Plastics
WATER PRESSUR	E AND DRAINAGE FLOW	 	☐ Freeze Damage or Danger
SUPPLY		OBSERVA	<u>TIONS</u>
Functional Flow	VENTING	☐ Drips or Leaks	☐ Noisy
Adequate Flow	Vented to Atmosphere Traps	☐ Improper Traps	□ Water Hammer
D WASTE	₩ Traps	Adequate	□ Water Running Sound
		∑ Functional	☐ Sweating
☐ Non Functional		☐ Non Functional Supply☐ Non Adequate Supply	☐ Sewage Odor
		☐ Non Functional Drainage	□ Open or Improper Vent
FIXTURES AN	D FAUCETS	OBSERVA	TIONS
FIXTURE MATERIAL	☐ Plastic	Sound DESCRIPA	
Cast Iron	Д∕Утуре	De Typical	☐ Trap Leak
□ Steel	Washer	☐ Temporary Repairs	Toile Loose of
∯ Plastic	Ø Washerless	Si Finish Damage CHO	Wet on Floor
Fiberglass	Ø TUBS	Sinks Loose IN TUS	☐ Toilet Damaged☐ Toilet Unused☐
D& China	Ø SINKS	☐ Spray Hose	☐ Fails to Flush
□ Marble	E TOILETS	☐ Faucets Loose	☐ Shower Pan Leak
FAUCETS	1 SHOWERS	☐ Faucets Drip or Leak	☐ S-traps
© Material	WHIRLPOOL TUBS	☐ Physical Damage	_ 3
D Brass	☐ STEAM BATH OR SAUNA	to Faucets	
HOT WATER S	<u>SOURCE</u>	OBSERVA	TIONS
TYPE		Sound	☐ Possible Asbestos
D Coo		D Typical	☐ No Pressure Relief
∐ Gas □ Oil	j	☐ Mechanical Damage	☐ Power or Fuel Off
☐ Domestic Coil		☐ Temporary Repairs	☐ Fuel Leaks
Other		☑ Corrosion	☐ Element Failed
	7540	☐ Drips or Leaks	□ Damaged Burner or Controls
PRIVATE SYST	EIVIS	OBSERVA [*]	IONS
☐ Supply Equipment☐ Waste Disposal		* Wells, springs, drain field:	s. cesspools and other private
Tradic Dispusal		supply and Waste Dispos	al Systems are not inspected.
Comments: C.A.:	INPRI TOP ALCO	1 1 0 1 1	

			5
LIMITATIONS TYPICAL RESTRICTED Crawlspace Inaccessible Attic Inaccessible Equipment Inaccessible	GENERAL System Inspected Power On Amateur Workmanship Main Panel Rating Panel Amps Volts Aluminum Wire/General	< 689 × × 688 × × 682 × × 684 × 684 × × 684 × × 684 × × 684 × × 684 × × 684 × × 684 × × 684 × 684 × ×	
	Shock Hazard Room For Future Expansion Subjective Rating	Y Y N E A M F	
EXTERIOR SERVICE AND METER ☐ Overhead Service (No. of Conductors) ☐ Underground Service ☐ Meter and Meter Base	⊠:Typical □ Obstruction/Damage □ Loose Missing Low □ □ Mast Damaged □	I Weather Head Loose Missing Low Not Supported Conduit Rusted/ Damaged Abandoned Equip./Wiring Cabinet Loose Rusted Damaged	
MAIN PANEL/SUBPANELS □ FUSE PANEL □ SUBPANELS □ BREAKER PANEL □ Fuse □ Main Breaker □ Breaker □ Split Buss □ OVERFUSING		Crowded Double Tap Mixed Metals	
WIRING SERVICE DROP/LATERAL GROUNDING & BONDING SERVICE ENTRANCE Grounding MATERIAL Bonding Copper Type Aluminum Romex Copper Metallic AMPACITY Knob and Tube Over Current Device Conduit Wiring Grounding Bonding Homex Copper Clad Copp	OBSERVAT □ Sound □ Typical □ Unsupported	TIONS Aluminum Wiring in 120 Volt Branch Circuits Metallic Cable Knob and Tubing Wiring nd	
INTERIOR COMPONENTS ☐ Receptacles ☐ Pull Chain ☐ Light Fixtures ☐ Recessed	OBSERVAT Das Sound Das Typical	TONS ☐ Improper Fixtures ☐ No GFCI	
	 □ No Ground/Bond □ Loose/Damaged Receptacles □ Improper Wired Receptacles □ Damaged/Broken Switches □ Damaged/Missing Fixtures 	☐ GFCI Broken ☐ No Smoke Detector ☐ Smoke Detector Broken ☐ Lack of Cover Plates	
EXTERIOR COMPONENTS Preceptacles Switches Switches Devices Lightning Rods	OBSERVAT Sound Typical No Ground/Bond Loose/Damaged Receptacles Improper Wired Receptacles Damaged/Broken Switches Damaged/Missing Fixtures	FIONS ☐ Improper Fixtures ☐ No GFCI ☐ GFCI Broken ☐ Lack of Cover Plates ☐ Damaged Lighting Systen ☐ Contact Hazard ☐ Inappropriate Wire	n
Comments:			

6	
FCTION	d

			r	
LIMITATIONS TYPICAL RESTRICTED No Fuel/Heat Off Pilot Light Out Failed to Respond Hazardous Non Inspected Access/Tank Equipment/Fireplace Inaccessible Not Tested As Heat Pump Solar System	Oil Selectric EQUIPMENT LOC THERMOSTAT TO Mechanical Selectronic THERMOSTAT LOC THERMOSTAT LOC THERMOSTAT LOC THERMOSTAT COC DOFunctional	☐ Heat Pump ☐ Wood ☐ Coal CATION ENT /PE ☐ Multiple ☐ Simultaneous DCATION	GENERAL Systems Ins Estimated A # of Zones/s Estimated R Active Fuel I Air/Water Le Rooms With Capacity Temperature Flame Color # of Fireplac Amateur Wo Subjective R	spected ge Systems lemaining Life Leaks laks lout Heat Rise ces orkmanship N N N N N N N N N N N N N N N N N N
WARM AIR SYSTEMS			000==:::	
FURNACE (HOT AIR) FURNACE (HOT AIR) Insulated Counter Flow Uninsulated Transite Gravity Heat Pump Electric Back Up Gas or Oil Back Up Water Source Fan Coil Water Heater DUCT WORK Note Duct Work Disposable Electronic		OBSERVATIONS Sound		
HYDDONIC EVETENC		- Dity Title		☐ Spillage/Back Drafting
HYDRONIC SYSTEMS BOILER Gravity Hot Water Circulated Steam Radiant Slab MATERIAL RADIATORS/CONVECTORS Cast Iron Cast Iron/Radiators Conversion Cast Iron/Baseboard DISTRIBUTION SYSTEM Copper/Tube Baseboard One Pipe Copper Tube Cabinets Two Pipe		☐ Sound ☐ Typical ☐ Clean ☐ Boiler Soote ☐ View/Comb ☐ Possible As ☐ System Agii ☐ Boiler Leaki ☐ Combustior Damage	Chamber Restrict bestos ng ng n Chamber	☐ Absence of Parts/Controls ☐ Heat or Cabinet Damage ☐ Piping Leaks ☐ Pipes Unsupported
SPACE HEATING			OBSERVA'	TIONS
☐ Floor Furnaces ☐ Electric B ☐ Stove/Inserts ☐ Heat Purn ☐ Wall Furnaces ☐ Radiant C ☐ Space Heaters ☐ Ductless Furnaces	ps/Wall	☐ Sound ☐ Typical ☐ Heat Exchar ☐ Physical Da	nger Damage E	TIONS Fan Failed Rusted Clearance Unvented
FIREPLACE/FLUES				TIONS
□ MASONRY □ FLUES □ Wood Burning □ Masonry □ Coal Burning □ Metal □ MANUFACTURED □ Transite □ Built In □ Connecto	r	☐ Sound ☐ Typical ☐ Clean ☐ Presentmen ☐ Spillage/Baq ☐ Sooted or C ☐ Damaged M	t	Flue Fire Missing or Damaged Damper Unlined Failed or Rusted Leaking at Flashing Cracked
Comments:		Darriaged W		Interior Uninspected
CUIIIIIGIIIS.				

Comments:

CEILINGS

ROOF

FLOORS WALLS FINISHED BASEMENT R-13 DO 19 2X4 WAUS PROB R-13 BATT W/BRICK R-17

N12' BLOWN CELLULOSE R-38 CERT.

LIMITATIONS	APPLIANCES	GENERAL SECTION
ŻØTYPICAL	<u> </u>	*
☐ RESTRICTED	Maximum	
☐ Interior Freshly	AD Range Burners	Clues/Tell Tale Signs Y Indications of Contaminants Y
Painted/Remodeled	☐ Grills	Amateur Workmanship
	☑ Hood Fans/Vents	Subjective Rating (EA)M F
	☐ Microwave	Cusjoon raming (LDT) W
	🔯 Garbage Disposer 💃	SUBJECTIVE RATING DEFINITIONS: E - EXCELLENT, A - AVERAGE,
	☐ Trash Compactor	M - MARGINAL, F - FAILURE
WALLS AND CEILING M	ATERIAL	OBSERVATIONS
☐ PLASTER \$ CERAN		
☐ Wood Lath		Ďa Sound į
☐ Rock Lath ☐ Mud S		∑ Typical
☐ Wire Lath ☐ BRICK	AND STONES	Functional
☐ Plaster or Blue Board		Stained CE 16,06 TUES
DRYWALL		☐ Cracked TOS2 TICE
☐ PANELING ☐ Solid Wood		Nail Pops Settlement o Sagging FZ 200 RS
☐ Solid Wood☐ Plywood Paneling		☐ Buckling
PACOUSTIC CEILING	•	☐ Holes
Tile (Block)		☐ Mold or Mildew
Propped Grid		☐ Missing or Damaged
FINISHED FLOORS		- DP Unlevel FLOOPS
		☐ Wood Rot
		☐ Lost Seals Insulated Glass
☐ Plank/Strip	** -	☐ Stuck or Closed Tight
= Guaii	y Marble	☐ Cracked or Broken Panes ☐ Missing Locks
Wall to Wall	viai bie	☐ Water Seeping
🖒 Loose Laid		☐ Misaligned
\$ SOFT TILE		☐ Failing Putty or Grout
Sheet Vinyl		☐ Missing or Broken Trim
☐ Block Tile		₩ Wear and Tear
RAILS AND STAIR	RS	Burned or Damaged
Handrails	<u></u>	☐ Broken or Loose Rails
Safety Rails		☐ Peeling Paint
Ø⊅Steps		☐ Sash Cord or Spring Balance ☐ Loose Plaster
☐ Balconies		D Loose Carpet STAINED
		☐ Truss Lift
		☐ Lead Paint
<u>ITEM</u>	GENERAL RATING	OBSERVATION
MALL S	E A M F	CHOLITATION
WALLS	n	
CEILINGS	1	
FINISHED FLOORS		
INTERIOR TRIM	ł	WELL
EXTERIOR OF CABINETS	8 1	-
SURFACE OF COUNTERTOPS	E-A	MAINTAINED
INTERIOR DOORS HARDWARE		
INTERIOR OF WINDOWS	1	
INTERIOR RAILS/STAIRS		
KITCHEN APPLIANCES	SUBJECTIVE RATING DEFINIT	IONS: E - EXCELLENT, A - AVERAGE, M - MARGINAL, F - FAILURE
Comments: ANGE	tof FINISH I	DAMAGED DISHWASHER NOF
		JUNE INO
		· · · · · · · · · · · · · · · · · · ·

Example of our competitor's report